

03500.015541.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
: Examiner: J.J. Maldonado
TAKAHIRO YAJIMA ET AL.)
: Group Art Unit: 2823
Appln. No.: 09/900,043)
:
Filed: July 9, 2001)
:
For: THIN FILM FORMATION METHOD)
:
U.S. Patent No.: US 6,800,539 B2)
:
Issued: October 5, 2004) January 13, 2005

Certificate
JAN 25 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

JAN 25 2005

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

A handwritten signature in cursive script, appearing to read "Peter Saxon", written over a horizontal line.

Peter Saxon
Attorney for Patentees
Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 465969v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,539 B2

DATED : October 5, 2004

INVENTOR(S) : TAKAHIRO YAJIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 27, "Mark ▼" should read --Mark ▲--.

COLUMN 7:

Line 42, "Mark ▼" should read --Mark ▲--.

COLUMN 8:

Line 55, "(Mark ▼" should read --(Mark ▲--; and

Line 59, "(Mark ▼" should read --(Mark ▲--.

COLUMN 10:

Line 38, "1000 sccm." should read --10000 sccm.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,539 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,539 B2

DATED : October 5, 2004

INVENTOR(S) : TAKAHIRO YAJIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 27, "Mark ▼" should read --Mark ▲--.

COLUMN 7:

Line 42, "Mark ▼" should read --Mark ▲--.

COLUMN 8:

Line 55, "(Mark ▼" should read --(Mark ▲--; and

Line 59, "(Mark ▼" should read --(Mark ▲--.

COLUMN 10:

Line 38, "1000 sccm." should read --10000 sccm.--.

Staple
Here
Only!

PRINTER'S TRIM LINE

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,539 B2

No. of add'l. copies
@ 30¢ per page

